



☐ **Head Office**
8701 - 102 Street
Clairmont, AB T8X 5G8
Bus: (780) 532-7350
Fax: (780) 532-7769

Pro-Pak

crate # 7

p1/2

For a complete list of operation centers visit: www.ipacservices.com

11147 20/61 Plate Flange RF-4-A Q:1)
21148 10/60 Grafoil gasket 380 O.D x 280 I.D Q:1)
21151 3/210 Flex joint 21A Q:1)
21151 3/211 Flex joint 21B Q:1)
21151 3/340 3" 150 spool 925mm x 890mm Q:1)
21161 3/10 1 1/2" JW Shunt Line c/w hose Q:1)
21161 3/30 1 1/2" AW Shunt Line c/w hose Q:1)
21161 3/30 Cat Strainer 155 Cone Q:1)
21161 3/40 Cat Strainer 157 cone Q:1)
21161 3/230 1 1/2" x 8" bolts for leveling Cat engine Q:2)
21161 3/240 1 1/2" x 3" bolts for flywheel Adapter Q:12)
21161 3/250 Coupling Q:1)
21161 3/70 5/8" x 3 3/4" studs c/w nuts Q:24) BT
21161 3/80 3/4" x 3 3/4" studs c/w nuts Q:4) BT
21161 3/90 1 1/2" 300 Gasket Q:1)
21161 3/100 2" 300 Gasket Q:4)
21161 3/110 4" 150 gasket for engine crank Q:1)
21161 3/120 5/8" x 3 1/2" studs/w/nuts for engine crank Q:8)
21161 3/170 3/8" x 2" MC Bolts Q:8)
21161 3/180 3/8" x 2" MC Bolts Q:8)
11121 10/1050 3/4" x 1 7/8" Bolts c/w nut & washer Q:18)
11121 20/2090 5/8" x 3 1/4" Bolts c/w nuts & washer Q:4)
11121 40/1280 3/4" 1 7/8" Bolts c/w nuts & washer Q:4)

11147 10/70 Grafoil gasket 455 O.D x 348 I.D Q:2)
11147 10/90 3/8" x 2 1/4" c/w nuts/washer Q:24)
11147 20/40 1 1/4" x 3" c/w nuts/washer Zinc Coated Q:24)
11147 20/70 Grafoil gasket 3" 150 Q:1)
11147 20/80 5/8" x 2 1/4" Bolts c/w nuts/washer Q:8)
11148 10/60 Grafoil gasket 380 O.D x 280 I.D Q:1)
11148 10/80 3/8" x 2 1/4" Bolts c/w nuts/washers Q:12)
11148 20/60 3/8" x 2 1/4" Bolts c/w nuts/washers Q:12)
11148 20/80 Grafoil gasket 380 O.D x 280 I.D Q:1)



☐ **Head Office**
8701 - 102 Street
Clairmont, AB T8X 5G8
Bus: (780) 532-7350
Fax: (780) 532-7769

Pro-Pak

crate #7

For a complete list of operation centers visit: www.ipacservices.com

p2/a

- 11151 180/120 6" 300 gasket SPWD Q:1)
- 11151 210/180 Garlock gasket 152mm x 89mm Q:2)
- 11151 220/40 Garlock gasket ~~(322)~~ 194mm x 143mm Q:2)
- 11151 240/50 $\frac{3}{4}$ " x 4" studs c/w nuts B7 Q:8)
- 11151 240/60 $\frac{3}{4}$ " x 6 $\frac{1}{2}$ " studs c/w nuts B7 Q:8)
- 11151 250/50 $\frac{3}{4}$ " x 4" studs c/w nuts B7 Q:8)
- 11151 250/60 $\frac{3}{4}$ " x 6 $\frac{1}{2}$ " studs c/w nuts B7 Q:8)
- 11151 270/91 Garlock gasket 194mm O.D x 143mm O.D Q:2)
- 11151 280/40 Garlock gasket 194mm ~~O.D~~ x 143mm ~~O.D~~ Q:2)
- 11151 300/50 $\frac{3}{4}$ " x 4" c/w nuts B7 Q:8)
- 11151 300/60 $\frac{3}{4}$ " x 6 $\frac{1}{2}$ " c/w nuts B7 Q:8)
- 11151 310/50 $\frac{3}{4}$ " x 4" c/w nuts B7 Q:8)
- 11151 310/60 $\frac{3}{4}$ " x 6 $\frac{1}{2}$ " c/w nuts B7 Q:8)
- 11151 330/101 Garlock gasket 194mm x 143mm Q:2)
- 11161 2/300 $\frac{3}{8}$ " x 1 $\frac{1}{4}$ " MC Bolts Q:40)
- 11161 3/210 $\frac{3}{8}$ " nuts Q:40)
- 11161 3/220 $\frac{3}{8}$ " lock washer Q:40)
- 11161 3/230 $\frac{3}{8}$ " Flat washers Q:80)
- 11161 3/270 1 $\frac{1}{2}$ " x 8" Fine thread bolts Q:6)
- 11161 3/280 1 $\frac{1}{2}$ " x 2 $\frac{3}{4}$ " Fine thread bolts Q:12)
- 11161 3/290 Fly wheel Adapter for Cat engine Q:1)
- 21147 20/30 Grafoil gasket 455 O.D x 348 I.D Q:2)
- 21148 20/60 Grafoil gasket 380 O.D x 280 I.D Q:1)